



**Application
Parameters**

Duct

Point Measurement

Output Signal Active Humidity:

DC 0...5 V, DC 0...10 V	22DTH-11M	
DC 0...5 V, DC 0...10 V	22DTH-11MM	
4...20 mA	22DTH-13M	
DC 0...5 V, DC 0...10 V	22DTH-15M	
DC 0...5 V, DC 0...10 V	22DTH-16M	

**Application
Parameters**



Outdoor

Output Signal Active Humidity:

DC 0...5 V, DC 0...10 V	22UTH-11		DC 0...5 V, DC 0...10 V	22UTH-150X	
DC 0...5 V, DC 0...10 V	22UTH-110M		DC 0...5 V, DC 0...10 V	22UTH-160X	
DC 0...5 V, DC 0...10 V	22UTH-110X				
4...20 mA	22UTH-13				
4...20 mA	22UTH-130X				