


Application  
Parameters



Pipe

Output Signal / Measuring Range Pressure:

DC 0...10 V / 0...1 bar	<b>22WDP-111</b>	4...20 mA / 0...1 bar	<b>22WDP-131</b>
DC 0...10 V / 0...2.5 bar	<b>22WDP-112</b>	4...20 mA / 0...2.5 bar	<b>22WDP-132</b>
DC 0...10 V / 0...4 bar	<b>22WDP-114</b>	4...20 mA / 0...4 bar	<b>22WDP-134</b>
DC 0...10 V / 0...6 bar	<b>22WDP-115</b>	4...20 mA / 0...6 bar	<b>22WDP-135</b>
DC 0...10 V / 0...4 bar	<b>22WP-114</b>	4...20 mA / 0...4 bar	<b>22WP-134</b>
DC 0...10 V / 0...6 bar	<b>22WP-115</b>	4...20 mA / 0...6 bar	<b>22WP-135</b>
DC 0...10 V / 0...10 bar	<b>22WP-116</b>	4...20 mA / 0...10 bar	<b>22WP-136</b>
DC 0...10 V / 0...16 bar	<b>22WP-117</b>	4...20 mA / 0...16 bar	<b>22WP-137</b>