



Application
Parameters

Duct

Point Measurement

Output Signal / Measuring range (differential Pressure):

Switch / 20...300 Pa	01APS-10R	
Switch / 50...500 Pa	01APS-10U	
Switch / 200...1000 Pa	01APS-101	
Switch / 500...2500 Pa	01APS-104	

With LCD-Display:

DC 0...5 V, DC 0...10 V	22ADP-154		DC 0...5 V, DC 0...10 V	22ADP-154L	
DC 0...5 V, DC 0...10 V	22ADP-156		DC 0...5 V, DC 0...10 V	22ADP-156L	
DC 0...5 V, DC 0...10 V	22ADP-15Q		DC 0...5 V, DC 0...10 V	22ADP-15QB	
DC 0...5 V, DC 0...10 V	22ADP-15QA		DC 0...5 V, DC 0...10 V	22ADP-15QL	

DC 0...5 V, DC 0...10 V 4...20 mA	22ADP-184		DC 0...5 V, DC 0...10 V 4...20 mA	22ADP-184L	
DC 0...5 V, DC 0...10 V 4...20 mA	22ADP-186		DC 0...5 V, DC 0...10 V 4...20 mA	22ADP-186L	
DC 0...5 V, DC 0...10 V 4...20 mA	22ADP-18Q		DC 0...5 V, DC 0...10 V 4...20 mA	22ADP-18QB*	
DC 0...5 V, DC 0...10 V 4...20 mA	22ADP-18QA*		DC 0...5 V, DC 0...10 V 4...20 mA	22ADP-18QL	

*Auto-Zero